03500.017818.



OIP	E 4298	П
DEC 0	7 500g Pr	11
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	To D	

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

m re Pa	tent of:)	
		:	Examiner: J. L. Williams
YOJI T	ERAMOTO)	
		:	Art Unit: 2879
Appln. No.: 10/758,193)	
		:	
Filed: January 16, 2004)	
		:	
For:	METHOD OF MANUFACTURING)	
	ELECTRON-EMITTING DEVICE,	:	
	METHOD OF MANUFACTURING)	
	ELECTRON SOURCE, AND METHOD	:	
	OF MANUFACTURING IMAGE)	
	DISPLAY DEVICE	:	•
)	
U.S. Patent No.: US 7,074,102 B2		:	
)	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Issued: July 11, 2006

Certificate

OFC 1 2 2006

Of Correction

December 6, 2006

46 T730044

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

DEC 1 3 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Frank A. I eLucia

Attorney for Patentee Registration No. 42,476

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

Facsimile: (212) 218-2200

NY_Main 603724v1

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,074,102 B2

DATED

July 11, 2006

INVENTOR(S) :

YOJI TERAMOTO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 9, "materials," should read -- the materials,--.

COLUMN 1:

Line 58, "JP 3010305" should read -- JP 3-10305--.

COLUMN 3:

Line 57, "electrode(first" should read --electrode (first--;

Line 59, "trode(second" should read --trode (second--; and

Line 60, "electrode(third" should read --electrode (third--.

COLUMN 6:

Line 57, "element(ex." should read --element (ex.--.

COLUMN 7:

Line 29, "an" (second occurrence) should be deleted;

Line 30, "a" should be deleted;

Line 32, "is" should read -- are--; and

Line 64, "is" should read -- are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

New York, New York 10112-380 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 603724v1 PATENT NO. <u>US 7,074,102 B2</u>

No. of add'l. copies @ 30¢ per page



DEC 1 3 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,074,102 B2

DATED

July 11, 2006

INVENTOR(S) :

YOJI TERAMOTO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

Line 1, "is" should read -- are --.

COLUMN 9:

Line 28, "(nor" should read --(not--; and Line 29, "solution 104:" should read --solution 104;--.

COLUMN 10:

Line 18, "solution 104:" should read --solution 104;--; and Line 34, "(catalytic," should read --(catalytic--.

COLUMN 11:

Line 5, "solution 104:" should read --solution 104;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 7,074,102 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow

MEC 1 3 2006

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,074,102 B2

DATED

July 11, 2006

INVENTOR(S) :

YOJI TERAMOTO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [57] ABSTRACT:

Line 9, "materials," should read -- the materials, --.

COLUMN 1:

Line 58, "JP 3010305" should read --JP 3-10305--.

COLUMN 3:

Line 57, "electrode(first" should read --electrode (first--;

Line 59, "trode(second" should read --trode (second--; and

Line 60, "electrode(third" should read --electrode (third--.

COLUMN 6:

Line 57, "element(ex." should read --element (ex.--.

COLUMN 7:

Line 29, "an" (second occurrence) should be deleted;

Line 30, "a" should be deleted;

Line 32, "is" should read -- are--; and

Line 64, "is" should read -- are--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY_Main 603724v1

PATENT NO. <u>US 7,074,102 B2</u>

No. of add'l. copies @ 30¢ per page

⇒ ____

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,074,102 B2

DATED

July 11, 2006

INVENTOR(S)

YOJI TERAMOTO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 8:

Line 1, "is" should read -- are--.

COLUMN 9:

Line 28, "(nor" should read --(not--; and Line 29, "solution 104:" should read --solution 104;--.

COLUMN 10:

Line 18, "solution 104:" should read --solution 104;--; and Line 34, "(catalytic," should read --(catalytic--.

COLUMN 11:

Line 5, "solution 104:" should read --solution 104;--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,074,102 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82) NY_Main 603724v1

12:12:20